

Work Order ID 73616

Wednesday, September 07, 2011 2:33:38 PM



Page 1

Item ID: D3463-042

Accept



Setup Start



Revision ID:

Stop



Item Name: Step Weldment Assembly

Start Date: 9/7/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 9/29/2011 Req'd Qty: 2.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

D3463

Rev B

100

0.00



Large Fab

Large Fab

Memo

0.00

Large Fab

Weld assembly as per dwg D3463 using DT8875

EL 12-1-5 (72)

110

QC9- Inspect visual per QS1004- Fusion Welds

0.00



QC

Memo

0.00

Quality Control

Pl 12.01.05

2x Ø

120

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

Sizalor

(72)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 73616

Wednesday, September 07, 2011 2:33:38 PM



Item ID: D3463-042

Accept



Setup Start



Revision ID:

Stop



Item Name: Step Weldment Assembly

Start Date: 9/7/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 9/29/2011 Req'd Qty: 2.00

Customer:

Reference:

Run Start



Approvals: Process Plan:

Date:

Tooling:

Date:

Stop



QC:

Date:

SPC (Y/N):

Date:

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID Tool # Plan Code Accept Qty Reject Qty Reject Number Insp. Stamp

130



Powdercoat

White Gloss(Ref:4.3.5.2) per QSI005 4.3-Steel

0.00

Memo

0.00

Powder Coating

1- Mask areas indicated on dwg D3463 (holes, threads)
START TIME: 9:20
OVEN TEMPERATURE: 400 F
FINISH TIME: 9:50

2 x of m-l 12/01/06

140



HandFinish

Wing Walk as per dwg QSI005 4.4 Batch 119094

0.00

Memo

0.00

Hand Finishing

2 BR 12-1-9.

150



QC

QC3- Inspect Part Finish

0.00

Memo

0.00

Quality Control

2 x of counted & identified. 12/01/09

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 73616

Wednesday, September 07, 2011 2:33:38 PM



Item ID: D3463-042

Accept



Setup Start



Revision ID:

Stop



Item Name: Step Weldment Assembly

Start Date: 9/7/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 9/29/2011 Req'd Qty: 2.00



Customer:

Reference:

Run Start



Approvals: Process Plan:

Date:

Tooling:

Date:

Stop



QC:

Date:

SPC (Y/N):

Date:

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID Tool # Plan Code Accept Qty Reject Qty Reject Number Insp. Stamp

160

Identify as per dwg & Stock Location

0.00



Packaging

Memo

0.00

Packaging

170

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

GP 12/01/10 (2)

12/1/10 JG

MF 12-01-10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, September 07, 2011 2:33:35 PM

Page 1

Work Order ID: 73616

Parent Item: D3463-042

Parent Item Name: Step Weldment Assembly



Start Date: 9/7/2011

Required Date: 9/29/2011

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP REV. A 05.11.18 new issue EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

238-806		Purchased	No			100	Each	64.0000	2	4			
SS DOWEL PIN 1" LONG													

Location	Loc Qty	Loc Code
----------	---------	----------

ST	64	
117606	64	

D3453-3		Manufactured	No			100	Each	4.0000	1	2			
Clevis													

Location	Loc Qty	Loc Code
----------	---------	----------

WA	4	
71900	4	

D3453-5		Manufactured	No			100	Each	1.0000	1	2			
Plug													

Location	Loc Qty	Loc Code
----------	---------	----------

WA023	1	
59204	1	

D3463-1		Manufactured	No			100	Each	4.0000	1	2			
Arm													

Location	Loc Qty	Loc Code
----------	---------	----------

WA	4	
70855	4	

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, September 07, 2011 2:33:36 PM

Page 2

Work Order ID: 73616

Parent Item: D3463-042

Parent Item Name: Step Weldment Assembly

Start Date: 9/7/2011

Required Date: 9/29/2011

Start Qty: 2.00

Required Qty: 2.00

D3463-3 Manufactured No

100 Each

12.0000

1 2



Step

Location

Loc Qty

Loc Code

WA025

12

46269

12

D3463-5 Manufactured No

100 Each

21.0000

2 4



End Cap

Location

Loc Qty

Loc Code

WA

21

70819

21

D3463-7 Manufactured No

100 Each

1.0000

1 2



Drag Arm

Location

Loc Qty

Loc Code

WA025

1

70857

1

73624

2

EL 12-1-4

2

EL 12-1-4.

4

EL 12-1-5

Wednesday, September 07, 2011 2:33:36 PM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART

DESIGN RF	DRAWN BY RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED #	DRAWING NO. D3463	REV. B SHEET 1 OF 4
DATE 05.12.05	TITLE STEP WELDMENT		SCALE 1:8
A	05.09.20	NEW ISSUE	
B	05.12.05	REVISE DIM.; D3463-5 WAS D3463-5F	

**NOTES:**

- 1) WELD PER DART QSI 004
- 2) FINISH: POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.010
- 6) IDENTIFY WITH DART P/N USING FINE POINT PERMANENT INK MARKER


COPYRIGHT © 2005 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART

DESIGN RF	DRAWN BY RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3463	REV. B SHEET 2 OF 4
DATE 05.12.05	TITLE STEP WELDMENT		SCALE 1:4

RELEASED

05.12.05 *[Signature]***D3463-1 ARM****NOTES:**

- 1) MATERIAL: AISI 316/304 SS SEAMLESS TUBING (REF. DART SPEC. M304TR1.000W.120)
 - 2) FINISH: NONE
 - 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) ALL DIMENSIONS ARE IN INCHES
 - 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.025
- 73616*

COPYRIGHT © 2005 BY DART AEROSPACE LTD.


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART

DESIGN RF	DRAWN BY RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED #	DRAWING NO. D3463	REV. B SHEET 3 OF 4
DATE 05.12.05		TITLE STEP WELDMENT	SCALE 1:4

RELEASED

05.12.05

**D3463-7 DRAG ARM****NOTES:**

- 1) MATERIAL: AISI 316/304 SS SEAMLESS TUBING (REF. DART SPEC. M304TR0.750W.120)
- 2) FINISH: NONE
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.010

73616

COPYRIGHT © 2005 BY DART AEROSPACE LTD.





THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART

DESIGN RF	DRAWN BY RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED #	DRAWING NO. D3463	REV. B SHEET 4 OF 4
DATE 05.12.05	TITLE STEP WELDMENT		SCALE 1:2

RELEASED

05.12.05 #

FORM USING
D3463-3T1**D3463-3F FLAT PATTERN****D3463-3 STEP****D3463-5 END CAP**
SCALE 1:1**NOTES:**

- 1) MATERIAL: AISI 304/316 SS SHEET, 0.060 THICK (REF. DART SPEC. M304S16GA)
- 2) FINISH: NONE
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.010

7 3666

COPYRIGHT © 2005 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.